

July 12, 2022 – Superintendent's Report ADMIN UPDATE:

Operational Data: Operational Data: June Totals SANITARY SEWER SYSTEM

- (22) Sanitary sewer lift station work-orders completed.
- (14) Sanitary sewer grinder pump station work-orders completed.
- (1) Sanitary sewer force main repair completed.
- (5074) LF of sanitary sewer main cleaned.
- (3) Sanitary sewer pumps rebuilt.
- Trimming trees around sanitary sewer lift stations.
- Cutting and trimming grass as needed at Utility properties.

# Water Distribution Underground Maintenance

- (4) Water main breaks repaired.
- (2) Water service line meter pits installed.
- (3) Water service lines repaired.
- (2) Concrete restorations performed in house.
- (9) Yard restorations completed.
- Maintained all street and sidewalk cuts until final restoration can be made.
- (1) Fire hydrant repaired.
- (21) Fire hydrants painted.
- (7) Water main valves exercised.
- (5) Water main shut outs performed.
- (11) Water line leak investigations performed.
- (22) Inspections for projects performed.
- Delivered door notifications for water main work on Zoeller Ave.
- (1) Water main fire flow tests performed.

# WATER PLANT/WELL ACTIVITY

Fort Harrison Water Plant

- Ongoing coordination with TCI and Wessler Engineering in getting new filter plant operational.
- Cutting and trimming grass as needed.
- Inspected backup generators (ran and checked fuel levels)
- Backwashed filters as needed.
- Rebuilt chlorine feed pumps.

Indian Lake Water Plant

- Ongoing coordination with TCI and Wessler Engineering in getting work completed at water plant.
- Cutting and trimming grass as needed.
- Peerless Midwest performed maintenance on high service pumps and well motors.
- Washed aerator screens.
- Worked with Wessler on SCADA updates.
- Inspected backup generators (ran and checked fuel levels)
- Had backup generator repaired.
- National Water Service was working on well 16 cleaning.
- Precision Instruments was working on raw water flow gauge.
- Reinstalling antenna at raw water meter vault.

Richardt Water Plant

- Cutting and trimming grass as needed.
- Washed aerator screens.
- B L Anderson was out to work on backwash valve and clean analyzer.
- LionHeart replaced temperature sensor on backup generator.

Winding Ridge Booster Station

• Cutting and trimming grass as needed.

52<sup>nd</sup> Street Tower

• Cutting and trimming grass as needed.

Oaklandon Tower

• Cutting and trimming grass as needed.

Water Quality Samples

• 50 water samples were taken from the distribution system and taken to an independent lab for testing.

Miscellaneous

- Well readings were taken.
- Fluoride samples were collected and taken to the State laboratory.
- Samples were collected for Well 16.

# **BUSINESS OFFICE/SERVICE DEPARTMENT**

# June totals to be provided on July 26, 2022 report

- Active accounts.
- Work orders completed.

# **BILLING ADJUSTMENTS:**

• 9736 English Oak Place - customer is requesting a sanitary sewer adjustment for \$421.14 due to a spigot leak. We recommend approval.